

Tickets

#	Projekt	Tracker	Status	Priorität	Thema	Zugewiesen an	Aktualisiert
720	Helios	Fehler	Neu	Normal	Eval-RTC: Strange behaviour when battery gets removed		09.12.2025 10:48
718	Helios	Fehler	Neu	Normal	Calculate voltage-divider for "Enable" MOSFETS	Maximilian Seesslen	11.12.2025 13:29
716	Helios	Fehler	Neu	Normal	Driver board: No level shifter for I2C	Maximilian Seesslen	02.12.2025 15:16
715	Helios	Fehler	Neu	Normal	Check I2C pullups		25.11.2025 18:33
713	liblepto	Feature	Neu	Normal	Make it compile for host computer	Maximilian Seesslen	21.11.2025 16:31
712	liblepto	Feature	Neu	Normal	CMake: No install target	Maximilian Seesslen	21.11.2025 16:25
709	libocelli	Feature	Neu	Normal	Use changeable framework		11.11.2025 16:26
707	Rufa	Feature	Neu	Normal	Housing	Maximilian Seesslen	04.11.2025 11:08
706	Rufa	Fehler	Neu	Normal	One pin is completely missing	Maximilian Seesslen	04.11.2025 11:03
705	Biwak	Fehler	Gelöst	Normal	MAX31855: Negative values are not calculated correctly	Maximilian Seesslen	03.11.2025 18:08
702	Rufa	Feature	Neu	Normal	Add fast readout command	Maximilian Seesslen	03.11.2025 14:47
698	CANHub	Feature	Neu	Normal	Dynamic port assigning	Maximilian Seesslen	29.09.2025 11:46
697	Biwak	Feature	Neu	Normal	Simulate touch display on Qt buard gui	Maximilian Seesslen	26.09.2025 15:56
696	Biwak	Fehler	In Bearbeitung	Normal	Touch: Whole processing is done in ISR	Maximilian Seesslen	26.09.2025 11:47
695	Biwak	Feature	Neu	Normal	Verify dynamic sleep	Maximilian Seesslen	25.09.2025 13:56
694	liblepto	Fehler	To be verified	Normal	CList: Add method for searching for item	Maximilian Seesslen	25.09.2025 09:51
693	Rufa	Feature	Neu	Normal	Simplify smoothener		24.09.2025 13:18
692	Biwak	Feature	To be verified	Normal	CRC: Make methods const.	Maximilian Seesslen	25.09.2025 13:16
691	CANRec	Feature	Neu	Normal	Specify timestamps	Maximilian Seesslen	24.09.2025 16:40
690	Biwak	Feature	To be verified	Normal	Retain: Use bigger data type than 8bit for counter	Maximilian Seesslen	25.09.2025 09:52
689	Biwak	Feature	To be verified	Normal	Allow more retain containers than two	Maximilian Seesslen	24.09.2025 17:21
688	Biwak	Fehler	To be verified	Normal	Host GUI: Pressing button does not result in interrupt	Maximilian Seesslen	25.09.2025 13:00
687	Biwak	Feature	To be verified	Normal	Blink modes: Use slower timings for host	Maximilian Seesslen	18.09.2025 13:32
685	liblepto	Feature	To be verified	Normal	Support expandable lists	Maximilian Seesslen	16.09.2025 13:26
684	liblepto	Feature	To be verified	Normal	Add unit tests for strings.	Maximilian Seesslen	16.09.2025 11:22
683	fosh	Feature	To be verified	Normal	Add support for backspace key	Maximilian Seesslen	17.09.2025 11:11
679	liblepto	Feature	To be verified	Normal	Implement CONFIG_LEPTO_RING_CUSTOM_DATA	Maximilian Seesslen	25.09.2025 13:23
677	fosh	Feature	Neu	Normal	Run on host natively	Maximilian Seesslen	15.09.2025 15:02
671	Biwak	Feature	To be verified	Normal	Implement dynamic sleep	Maximilian Seesslen	25.09.2025 13:56
663	Biwak	Feature	Neu	Normal	Document tipps and tricks	Maximilian Seesslen	17.09.2025 10:44
654	TCB	Feature	Neu	Normal	GCC 15 is out	Maximilian Seesslen	14.05.2025 14:22

#	Projekt	Tracker	Status	Priorität	Thema	Zugewiesen an	Aktualisiert
653	Campo	Feature	Neu	Normal	implement font converter	Maximilian Seesslen	13.11.2025 11:40
644	CANRec	Feature	Neu	Normal	Find first replay block fast	Maximilian Seesslen	24.09.2025 15:16
641	Canbridge	Test	Neu	Normal	Enable source section-id; Inject message from radio with too low package-ID, expect exception		10.04.2025 20:33
640	Canbridge	Test	Neu	Normal	Enable source section-id; Inject message from radio with too high package-ID, expect exception		10.04.2025 20:33
639	Canbridge	Test	Neu	Normal	Inject message via CAN, expect it on radio as broadcast. Don't acknowledge it. Expect further messages.		10.04.2025 20:33
638	Canbridge	Test	Neu	Normal	Inject message via CAN, expect it on radio as broadcast. Acknowledge it. Don't expect further messages.		10.04.2025 20:33
637	Canbridge	Test	Neu	Normal	Inject same message from radio, expect another ACK on radio		10.04.2025 20:33
636	Canbridge	Test	Neu	Normal	Inject an message from radio, expect ACK on radio	Maximilian Seesslen	10.04.2025 20:32
635	Canbridge	Test	Neu	Normal	Expect section-id to vanish from section-mask after timeout	Maximilian Seesslen	10.04.2025 20:32
634	Canbridge	Test	Neu	Normal	Inject heartbeat from radio, expect section-id in section-mask	Maximilian Seesslen	10.04.2025 20:32
628	Biwak	Feature	To be verified	Normal	use 128 bit UID	Maximilian Seesslen	17.09.2025 14:39
625	CANHub	Feature	Neu	Normal	Add websocket server	Maximilian Seesslen	18.03.2025 17:40
622	pics	Fehler	Neu	Normal	pic2		13.03.2025 20:25
621	pics	Fehler	Neu	Normal	bilder		13.03.2025 20:19
619	mainSwitch	Fehler	Neu	Normal	LM25056: Current calculated wrongly		11.03.2025 15:37
615	mainSwitch	Feature	Neu	Normal	Verseion 2: more power, RTC		28.02.2025 11:44
614	Squeezer	Fehler	Neu	Normal	Errors are not handled reliable		03.03.2025 16:39
611	libcampo	Feature	Neu	Normal	Bringup: verify/calibrate crystals	Maximilian Seesslen	25.09.2025 14:10
608	Mainswitch	Feature	Neu	Normal	Shutdown command	Maximilian Seesslen	29.01.2025 16:57
603	libcampo	Feature	Neu	Normal	Vagus: CAN: use filters	Maximilian Seesslen	22.01.2025 14:24
595	Kokon	Feature	Neu	Normal	Check board id and revision before flashing	Maximilian Seesslen	15.01.2025 15:12
593	libcampo	Feature	Neu	Normal	hwdata: clean up	Maximilian Seesslen	13.01.2025 15:38
587	Squeezer	Feature	Neu	Normal	Readme is missing	Maximilian Seesslen	18.12.2024 13:54
586	Biwak	Feature	Neu	Normal	Test implementation of eventLoop class	Maximilian Seesslen	27.11.2024 13:55
582	CANDis	Feature	Neu	Normal	change TDT command to set/get time/date to time_t	Maximilian Seesslen	12.11.2024 16:13
579	TCB	Feature	Neu	Normal	Generate list of packages	Maximilian Seesslen	11.11.2024 10:57
578	TCB	Fehler	Neu	Normal	Python from host is involved	Maximilian Seesslen	11.11.2024 10:55
577	TCB	Fehler	Neu	Hoch	Not all binaries get patched to use own interpreter	Maximilian Seesslen	11.11.2024 14:48
567	Biwak	Feature	Neu	Normal	Clean up heart-beat-LED-code	Maximilian Seesslen	17.09.2025 10:49
566	theme_noto	Feature	Neu	Normal	create const icon references	Maximilian Seesslen	09.01.2025 16:06

#	Projekt	Tracker	Status	Priorität	Thema	Zugewiesen an	Aktualisiert
558	CANDis	Fehler	Neu	Normal	Reading touch calibration is very unreliable	Maximilian Seesslen	07.10.2024 14:50
557	CANDis	Fehler	Neu	Normal	When switchin from "minutnik running items" to clock, background of letters are violet	Maximilian Seesslen	27.08.2024 22:41
553	CANHub	Feature	Neu	Normal	implement monitor mode	Maximilian Seesslen	08.09.2025 14:58
552	CANHub	Feature	Neu	Normal	Implement Heartbeat	Maximilian Seesslen	23.08.2024 13:42
550	TDTPrompt	Feature	Neu	Normal	Show CANHub connector status on status bar	Maximilian Seesslen	20.08.2024 15:07
547	CANHub	Feature	Neu	Normal	Loop detection	Maximilian Seesslen	15.08.2024 16:12
546	CANHub	Feature	Neu	Normal	multiple servers	Maximilian Seesslen	15.08.2024 16:01
544	CANHub	Fehler	Neu	Normal	Connectors: tolerate wrong sizes	Maximilian Seesslen	15.08.2024 15:23
517	Sensemux SW	Feature	Neu	Normal	Why does mainswitch stabelize values?		24.04.2024 12:08
514	CANSwitch	Feature	Neu	Normal	Test arena generated handler structure	Maximilian Seesslen	05.02.2025 16:30
511	Mainswitch	Requirement	Neu	Normal	An keep-awake-event via CAN should extend shutdown timeout	Maximilian Seesslen	06.09.2024 11:22
510	Mainswitch	Requirement	Neu	Normal	timeout shutdown	Maximilian Seesslen	06.09.2024 11:19
501	CANSwitch	Test	Neu	Normal	Send wanna-sleep		17.04.2024 18:22
497	libcampo	Feature	Neu	Normal	campo.sh: add changeLogSubmodules	Maximilian Seesslen	26.02.2024 18:31
495	Minutnik elnk	Unterstützung	Neu	Normal	Are both wakeups working correctly	Maximilian Seesslen	23.02.2024 13:22
494	Minutnik elnk	Unterstützung	Neu	Normal	Does UART-RX need Pullu por -down?	Maximilian Seesslen	23.02.2024 13:21
489	CANSwitch	Test	Neu	Normal	Send keep-alive	Maximilian Seesslen	17.04.2024 18:22
488	CANSwitch	Test	Neu	Normal	Fading out before timeout	Maximilian Seesslen	17.04.2024 18:22
486	CANSwitch	Test	In Bearbeitung	Normal	timeout warning	Maximilian Seesslen	11.02.2024 07:43
474	campoTemplate	Fehler	Neu	Normal	Git history is not reset	Maximilian Seesslen	19.01.2024 17:47
473	campoTemplate	Fehler	Neu	Normal	There is no actual template for README.md		19.01.2024 15:21
471	mainSwitch	Fehler	Neu	Niedrig	Wakeup-Button is not working	Maximilian Seesslen	05.02.2024 22:54
463	Canbridge	Feature	Neu	Normal	support bootcounter in config	Maximilian Seesslen	27.12.2023 17:12
454	Rufa	Feature	Neu	Normal	Verify smoothener		04.11.2025 10:57
443	Mito	Feature	Neu	Normal	implement validate mode	Maximilian Seesslen	20.11.2023 15:54
442	Canbridge	Feature	Neu	Normal	Use listening mode	Maximilian Seesslen	20.11.2023 15:32
441	Canbridge	Feature	Neu	Normal	Measure current consumption in RX mode	Maximilian Seesslen	20.11.2023 15:31
439	Canbridge	Fehler	Neu	Normal	Check RSSI instead of delaying	Maximilian Seesslen	20.11.2023 15:05
435	mainSwitch	Fehler	Neu	Normal	Power supply on CANBus is very poor		14.11.2023 14:48
431	Rufa	Feature	Neu	Normal	Introduce more noise filtering		04.11.2025 11:01
429	Canbridge	Feature	Neu	Normal	Multi-Nodes	Maximilian Seesslen	20.11.2023 15:10
428	Canbridge	Feature	Neu	Normal	Retransmit Messages	Maximilian Seesslen	27.10.2023 13:26

#	Projekt	Tracker	Status	Priorität	Thema	Zugewiesen an	Aktualisiert
426	Rufa	Fehler	Neu	Normal	Footprint fuer thermocouple-Kupplung hat fehler	Maximilian Seesslen	15.09.2023 11:28
425	Cablemeter	Feature	Neu	Normal	PCB: missing info for 3V	Maximilian Seesslen	12.09.2023 12:03
421	CANBuz	Feature	Neu	Normal	Create sinewave for DAC/DMA	Maximilian Seesslen	28.08.2023 18:52
420	libscapus	Feature	Neu	Normal	bme680: calculate absolute humidity	Maximilian Seesslen	14.08.2023 15:04
418	libcampo	Feature	Neu	Normal	campo.sh: verify "release" function	Maximilian Seesslen	20.07.2023 14:19
416	MWidgets	Feature	Neu	Normal	CPlotter: show date when time range is too big	Maximilian Seesslen	13.07.2023 16:12
388	NUC64DEBUG	Feature	Neu	Normal	use bigger buttons	Maximilian Seesslen	27.03.2023 14:24
369	CANIO	Feature	Neu	Normal	Send alarm on I2C error	Maximilian Seesslen	01.03.2023 11:43
365	Cordyceps	Feature	Neu	Normal	Show event marker in plots	Maximilian Seesslen	13.07.2023 13:55
364	Sensemux SW	Feature	Neu	Normal	evaluate more values	Maximilian Seesslen	13.02.2023 17:28
363	Cordyceps	Feature	Neu	Normal	Show marker in plots	Maximilian Seesslen	11.07.2023 16:36
357	TCB	Fehler	Neu	Normal	python-host: on debian pip and setuptools are not created automatically	Maximilian Seesslen	02.02.2023 14:31
355	TCB	Feature	Neu	Normal	activate chroot tests again	Maximilian Seesslen	22.05.2024 10:33
354	TCB	Fehler	Neu	Normal	autoconf directory from host is used	Maximilian Seesslen	02.02.2023 11:40
350	fosh	Feature	Neu	Normal	implement generic subcommands	Maximilian Seesslen	24.01.2023 18:23
349	Mainswitch	Requirement	Neu	Normal	Low voltage alert	Maximilian Seesslen	06.09.2024 11:19
345	libcampo	Feature	Neu	Normal	unit tests: parse hwinfo files	Maximilian Seesslen	28.11.2023 14:15
342	CANDis	Feature	Neu	Normal	USB CDC tester	Maximilian Seesslen	02.02.2023 11:56
327	Minutnik elnk	Fehler	Neu	Normal	Power consumption too high	Maximilian Seesslen	09.01.2023 13:26
317	PhonyBL	Feature	Neu	Normal	Implement big Statemachine	Maximilian Seesslen	21.11.2022 13:41
311	Biwak	Feature	Neu	Normal	Implement DMA USB	Maximilian Seesslen	17.09.2025 10:50
290	Minutnik elnk	Fehler	Neu	Normal	Yellow and red LEDs are quite dark	Maximilian Seesslen	26.10.2022 14:38
271	Minutnik elnk	Fehler	Neu	Normal	consumption tests completely missing	Maximilian Seesslen	14.10.2022 15:57
270	Minutnik elnk	Feature	Neu	Normal	Font in SPI-Flash	Maximilian Seesslen	29.11.2022 10:12
248	miniminutnik	Fehler	Neu	Normal	hw v0.2.x: add quirk to board file for UART pulldown	Maximilian Seesslen	14.08.2023 12:36
242	libocelli	Feature	Neu	Normal	implement png reader	Maximilian Seesslen	12.01.2023 19:00
241	Biwak	Feature	Neu	Normal	implement SPI DMA transmit	Maximilian Seesslen	17.09.2025 10:50
233	mainSwitch	Feature	Neu	Normal	Switch via photodiode	Maximilian Seesslen	11.12.2022 17:39
210	mainSwitch	Fehler	Neu	Normal	PCB routing problem	Maximilian Seesslen	01.02.2024 14:27
187	sensemux	Unterstützung	Neu	Normal	Bringup HW v0.2.x	Maximilian Seesslen	24.01.2023 13:59
186	Sensemux SW	Fehler	Neu	Normal	RTC does not store date	Maximilian Seesslen	13.02.2023 17:17
185	CANDis	Feature	Neu	Niedrig	Evaluate RTC calibration	Maximilian Seesslen	02.02.2023 13:12
176	Campo	Feature	Neu	Normal	create custom targets to cmake file to create and deploy documents	Maximilian Seesslen	27.06.2022 18:23

#	Projekt	Tracker	Status	Priorität	Thema	Zugewiesen an	Aktualisiert
144	Campo	Feature	Neu	Normal	implement hwdata stterm command		24.11.2023 14:38
135	Hardware	Unterstützung	Neu	Normal	Create BOM creator script with warehouse fields	Maximilian Seesslen	13.01.2022 15:30
75	libcampo	Unterstützung	Neu	Normal	bringup: Create test to write internal flash	Maximilian Seesslen	19.12.2023 16:49
32	Hardware	Fehler	Neu	Normal	Move the notes from "warehouse" to redmine.	Maximilian Seesslen	13.08.2021 12:56
31	NUC64DEBUG	Fehler	Neu	Niedrig	BOOT0 Button pulls pin low instead of high		13.08.2021 12:56
13	Minutnik	Fehler	Neu	Normal	Buttons do not fit		17.08.2021 13:24