

Hardware

	2025-12					2026-1					2026-2					2026-3					2026-4					2026-5				
	49	50	51	52	1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22				
Hardware																														
Move the notes from "warehouse" to redmine.																														
Create BOM creator script with warehouse (...)																														
Cablemeter																														
PCB: missing info for 3V																														
CANBuz																														
Create sinewave for DAC/DMA																														
Helios																														
Check I2C pullups																														
Driver board: No level shifter for I2C																														
Calculate voltage-divider for "Enable" (...)																														
Eval-RTC: Strange behaviour when battery (...)																														
mainSwitch																														
PCB routing problem																														
Switch via photodiode																														
Power supply on CANBus is very poor																														
Wakeup-Button is not working																														
Verseion 2: more power, RTC																														
LM25056: Current calculated wrongly																														
Minutnik																														
Buttons do not fit																														
Minutnik eInk																														
Does UART-RX need Pullu por -down?																														
Minutnik eInk - v0.2.x																														
consumption tests completely (...)																														
Yellow and red LEDs are quite (...)																														
Power consumption too high																														
Are both wakeups working correctly																														

NUC64DEBUG

use bigger buttons

NUC64DEBUG - v0.3.x

BOOT0 Button pulls pin low instead (...)

Rufa

Footprint fuer thermocouple-Kupplung (...)

Introduce more noise filtering

One pin is completely missing

Housing

sensemux

Bringup HW v0.2.x